

## **Appendix D**

### **Matrix Method Priority List**

The attached list indicates approximately the first \$10 million worth of road treatments according to the Matrix Method.

**Matrix Method Priority List (First \$10 million only)**

Priority Rank	Street Name	From Address	To Address	PCI	Repair Type	Matrix Score	Repair Cost
1	CITRUS AVE	1119	1127	29	*Mill + 2" RAC Overlay	95	\$9,375.00
2	COLTON AVE	701	717	61	*Rubberized THIN OVERLAY	95	\$12,691.00
3	COLTON AVE	701	799	55	*Rubberized THIN OVERLAY	88	\$12,224.00
4	CITRUS AVE	1101	1105	29	*Mill + 2" RAC Overlay	86	\$11,255.00
5	CITRUS AVE	1601	1689	27	*Mill + 2" RAC Overlay	84	\$66,846.00
6	BARTON RD	1321	1399	70	LOCALIZED BASE REPAIR / REPAVE	83	\$118,205.00
7	FERN AVE	901	913	61	*Rubberized THIN OVERLAY	83	\$11,559.00
8	GROVE ST	411	599	55	LOCALIZED BASE REPAIR / REPAVE	83	\$33,626.00
9	SAN BERNARDINO AVE	101	199	72	LOCALIZED BASE REPAIR / REPAVE	82	\$39,600.00
10	BROOKSIDE AVE	1259	1265	60	LOCALIZED BASE REPAIR / REPAVE	82	\$56,078.00
11	TENNESSEE ST	71	99	64	LOCALIZED BASE REPAIR / REPAVE	81	\$70,320.00
12	FERN AVE	401	499	74	*Rubberized THIN OVERLAY	81	\$16,805.00
13	FERN AVE	801	829	61	*Rubberized THIN OVERLAY	80	\$13,847.00
14	REDLANDS BLVD	0	0	60	*Rubberized THIN OVERLAY	80	\$4,564.00
15	CITRUS AVE	1691	1699	55	*Rubberized THIN OVERLAY	80	\$9,683.00
16	JUDSON ST	601	639	31	*Mill + 2" RAC Overlay	79	\$22,260.00
17	SAN BERNARDINO AVE	401	599	81	Rubberized thin overlay	79	\$14,052.00
18	JUDSON ST	921	939	34	*Mill + 2" RAC Overlay	78	\$17,793.00
19	TEXAS ST	901	943	72	LOCALIZED BASE REPAIR / REPAVE	78	\$42,912.00
20	JUDSON ST	641	649	31	*Mill + 2" RAC Overlay	78	\$7,680.00
21	CYPRESS AVE	601	623	29	*Mill + 2" RAC Overlay	78	\$13,974.00
22	COLTON AVE	1691	1699	80	Rubberized thin overlay	77	\$5,646.00
23	CYPRESS AVE	201	333	60	*Rubberized THIN OVERLAY	77	\$22,100.00
24	JUDSON ST	1167	1257	24	*Full Reconstruction (Major)	77	\$154,592.00
25	OXFORD DR	927	1031	20	*Full Reconstruction (LOCAL)	77	\$41,114.00
26	COLTON AVE	201	227	35	*Mill + 2" RAC Overlay	77	\$13,220.00
27	BARTON RD	1301	1319	72	Rubberized thin overlay	77	\$5,297.00
28	BROOKSIDE AVE	1267	1299	72	Rubberized thin overlay	77	\$3,013.00
29	FERN AVE	1125	1143	56	*Rubberized THIN OVERLAY	77	\$9,753.00
30	SYLVAN BLVD	1201	1299	29	*1.5 grind and overlay	77	\$22,210.00
31	COOK ST	403	599	24	Full Reconstruction	77	\$55,429.00
32	FORD ST	1501	1625	24	*Full Reconstruction (Major)	77	\$374,905.00
33	COLTON AVE	401	423	38	*Mill + 2" RAC Overlay	77	\$14,190.00
34	CYPRESS AVE	1341	1351	62	LOCALIZED BASE REPAIR / REPAVE	77	\$36,432.00
35	GROVE ST	611	633	55	LOCALIZED BASE REPAIR / REPAVE	77	\$28,672.00
36	PALM AVE	727	739	29	*Mill + 2" RAC Overlay	77	\$12,163.00

**Matrix Method Priority List (First \$10 million only)**

Priority Rank	Street Name	From Address	To Address	PCI	Repair Type	Matrix Score	Repair Cost
37	SAN MATEO ST	801	827	29	*Mill + 2" RAC Overlay	77	\$21,384.00
38	JUDSON ST	1101	1151	24	*Full Reconstruction (Major)	77	\$167,184.00
39	BROOKSIDE AVE	1231	1257	63	LOCALIZED BASE REPAIR / REPAVE	77	\$50,266.00
40	CAJON ST	401	455	70	Rubberized thin overlay	77	\$15,142.00
41	CYPRESS AVE	601	673	61	*Rubberized THIN OVERLAY	77	\$24,299.00
42	BROOKSIDE AVE	1201	1229	63	LOCALIZED BASE REPAIR / REPAVE	77	\$52,332.00
43	CITRUS AVE	1781	1799	31	*Mill + 2" RAC Overlay	76	\$19,800.00
44	FERN AVE	1101	1119	56	*Rubberized THIN OVERLAY	76	\$11,122.00
45	REDLANDS BLVD	2071	2099	56	LOCALIZED BASE REPAIR / REPAVE	76	\$14,832.00
46	CITRUS AVE	1149	1249	40	*Mill + 2" RAC Overlay	76	\$18,950.00
47	CITRUS AVE	1129	1147	42	*Mill + 2" RAC Overlay	75	\$18,850.00
48	OXFORD DR	1101	1231	70	LOCALIZED BASE REPAIR / REPAVE	75	\$61,235.00
49	CENTRAL AVE	1201	1229	23	Full Reconstruction	75	\$81,704.00
50	UNIVERSITY ST	1401	1419	24	*Full Reconstruction (MINOR)	75	\$61,286.00
51	FERN AVE	301	319	77	Rubberized thin overlay	75	\$7,930.00
52	CORNELL AVE	1101	1199	21	*Full Reconstruction (LOCAL)	75	\$84,147.00
53	CITRUS AVE	0	0	37	*Mill + 2" RAC Overlay	74	\$8,650.00
54	CYPRESS AVE	701	977	32	*Mill + 2" RAC Overlay	74	\$72,902.00
55	SAN MATEO ST	829	931	28	*Mill + 2" RAC Overlay	74	\$12,776.00
56	CENTER ST	19	99	61	LOCALIZED BASE REPAIR / REPAVE	73	\$81,384.00
57	CYPRESS AVE	1001	1019	36	*Mill + 2" RAC Overlay	73	\$14,061.00
58	JUDSON ST	1451	1499	20	*Full Reconstruction (Major)	73	\$61,824.00
59	COLTON AVE	123	131	38	*Mill + 2" RAC Overlay	73	\$3,920.00
60	BROCKTON AVE	757	769	32	*Mill + 2" RAC Overlay	73	\$10,272.00
61	TRIBUNE ST	1101	1225	35	*1.5 grind and overlay	73	\$29,479.00
62	FERN AVE	1201	1207	33	*Mill + 2" RAC Overlay	73	\$9,272.00
63	FORD ST	1635	1657	12	*Full Reconstruction (Major)	73	\$137,952.00
64	HERALD ST	1001	1027	26	*1.5 grind and overlay	73	\$12,025.00
65	BROCKTON AVE	1301	1375	55	LOCALIZED BASE REPAIR / REPAVE	73	\$54,752.00
66	COOK ST	101	199	28	*1.5 grind and overlay	73	\$8,081.00
67	TEXAS ST	251	299	56	LOCALIZED BASE REPAIR / REPAVE	73	\$15,360.00
68	BROCKTON AVE	1377	1399	60	*Rubberized THIN OVERLAY	73	\$9,383.00
69	JUDSON ST	201	217	35	*Mill + 2" RAC Overlay	73	\$22,614.00
70	LUGONIA AVE	401	499	38	*Mill + 2" RAC Overlay	73	\$19,140.00
71	JUDSON ST	1153	1165	24	*Full Reconstruction (Major)	73	\$77,040.00
72	JUDSON ST	901	919	34	*Mill + 2" RAC Overlay	73	\$17,307.00

**Matrix Method Priority List (First \$10 million only)**

Priority Rank	Street Name	From Address	To Address	PCI	Repair Type	Matrix Score	Repair Cost
73	FERN AVE	1251	1299	31	*Mill + 2" RAC Overlay	73	\$9,457.00
74	OCCIDENTAL DR	801	899	28	2inch Grind Overlay	72	\$15,728.00
75	BROCKTON AVE	601	699	33	*Mill + 2" RAC Overlay	72	\$10,896.00
76	CYPRESS AVE	979	999	38	*Mill + 2" RAC Overlay	72	\$11,552.00
77	OLIVE AVE	1201	1225	29	*Mill + 2" RAC Overlay	72	\$26,106.00
78	CITRUS AVE	1107	1117	37	*Mill + 2" RAC Overlay	72	\$12,580.00
79	SYLVAN BLVD	1101	1153	24	Full Reconstruction	72	\$139,115.00
80	OLIVE AVE	1631	1643	21	*Full Reconstruction (MINOR)	72	\$93,792.00
81	BROCKTON AVE	401	449	30	*Mill + 2" RAC Overlay	72	\$10,656.00
82	ALTA ST	1101	1159	71	CRACK FILL	71	\$1,067.00
83	HERALD ST	901	941	17	*Full Reconstruction (LOCAL)	71	\$38,110.00
84	COLTON AVE	301	309	38	*Mill + 2" RAC Overlay	71	\$8,420.00
85	PARKWOOD DR	107	147	60	*Crack Repair and SLURRY SEAL	71	\$4,954.00
86	NEVADA ST	501	799	70	LOCALIZED BASE REPAIR / REPAVE	71	\$106,112.00
87	CHAPEL ST	701	799	26	*1.5 grind and overlay	71	\$13,177.00
88	JUDSON ST	1001	1079	37	*Mill + 2" RAC Overlay	71	\$17,739.00
89	CENTRAL AVE	701	799	24	Full Reconstruction	71	\$38,584.00
90	OCCIDENTAL DR	901	933	22	Full Reconstruction	71	\$48,754.00
91	PALM AVE	1001	1061	23	*Full Reconstruction (MINOR)	71	\$153,466.00
92	EDWARDS ST	1201	1299	30	*1.5 grind and overlay	71	\$16,018.00
93	ARDMORE AVE	701	711	24	Full Reconstruction	71	\$29,557.00
94	TRIBUNE ST	901	937	28	*1.5 grind and overlay	71	\$13,497.00
95	CRAIG CT	201	217	60	*Crack Repair and SLURRY SEAL	71	\$2,772.00
96	CENTRAL AVE	801	915	20	Full Reconstruction	71	\$122,629.00
97	CLAY ST	1501	1535	70	CRACK FILL	71	\$1,078.00
98	PALM AVE	219	239	70	*Rubberized THIN OVERLAY	71	\$19,538.00
99	PIONEER AVE	423	641	61	LOCALIZED BASE REPAIR / REPAVE	71	\$59,508.00
100	SAN MATEO ST	601	643	40	*Mill + 2" RAC Overlay	71	\$41,364.00
101	OCCIDENTAL DR	1001	1033	29	2inch Grind Overlay	71	\$15,504.00
102	PARK AVE	26591	26599	28	2inch Grind Overlay	71	\$10,617.00
103	BERKELEY DR	901	999	26	*1.5 grind and overlay	71	\$13,159.00
104	ARDMORE AVE	713	717	24	Full Reconstruction	71	\$14,943.00
105	SUNSET DR	331	357	23	*Full Reconstruction (MINOR)	71	\$85,985.00
106	6TH ST	1301	1329	22	Full Reconstruction	71	\$22,221.00
107	COLLEGE AVE	901	945	27	*1.5 grind and overlay	71	\$19,947.00
108	BERKELEY DR	1001	1023	27	*1.5 grind and overlay	71	\$13,171.00

**Matrix Method Priority List (First \$10 million only)**

Priority Rank	Street Name	From Address	To Address	PCI	Repair Type	Matrix Score	Repair Cost
109	GRANT ST	201	257	16	*Full Reconstruction (LOCAL)	71	\$56,303.00
110	ROOSEVELT RD	0	0	20	*Full Reconstruction (LOCAL)	71	\$19,094.00
111	DIVISION ST	701	799	14	*Full Reconstruction (LOCAL)	71	\$37,205.00
112	DOYLE AVE	242	232	27	2inch Grind Overlay	71	\$8,129.00
113	FORD ST	1701	1799	15	*Full Reconstruction (Major)	71	\$95,520.00
114	DEVON PL	1101	1257	16	*Full Reconstruction (LOCAL)	71	\$87,629.00
115	HIGHLAND AVE	1501	1549	20	Full Reconstruction	71	\$71,120.00
116	PALM AVE	101	213	60	LOCALIZED BASE REPAIR / REPAVE	71	\$59,331.00
117	JUDSON ST	1401	1449	20	*Full Reconstruction (Major)	71	\$61,376.00
118	SAN BERNARDINO AVE	801	999	32	*Mill + 2" RAC Overlay	71	\$66,470.00
119	PALM AVE	1351	1355	70	*Rubberized THIN OVERLAY	71	\$5,281.00
120	JUDSON ST	1351	1399	22	*Full Reconstruction (Major)	71	\$61,376.00
121	COLTON AVE	1001	1025	38	*Mill + 2" RAC Overlay	70	\$5,340.00
122	SAN MATEO ST	1	19	49	*Mill + 2" RAC Overlay	70	\$34,344.00
123	PALM AVE	1313	1349	70	*Rubberized THIN OVERLAY	70	\$24,724.00
124	BROOKSIDE AVE	1301	1449	16	*Full Reconstruction (LOCAL)	70	\$231,235.00
125	UNIVERSITY ST	421	599	37	*Mill + 2" RAC Overlay	70	\$30,126.00
126	COLTON AVE	101	117	38	*Mill + 2" RAC Overlay	70	\$8,320.00
127	CYPRESS AVE	1021	1029	36	*Mill + 2" RAC Overlay	70	\$16,019.00
128	BROCKTON AVE	799	819	36	*Mill + 2" RAC Overlay	70	\$10,880.00
129	WASHINGTON ST	1601	1649	20	*Full Reconstruction (LOCAL)	70	\$56,243.00
130	COLTON AVE	1027	1079	38	*Mill + 2" RAC Overlay	70	\$8,880.00
131	GARDEN ST	1501	1553	24	*Full Reconstruction (Major)	70	\$197,811.00
132	HOME PL	601	699	25	*1.5 grind and overlay	70	\$21,148.00
133	ALABAMA ST	1	39	40	*Mill + 2" RAC Overlay	70	\$27,630.00
134	BERMUDA DR	601	627	24	Full Reconstruction	70	\$49,050.00
135	HIGHLAND AVE	901	1057	29	*Mill + 2" RAC Overlay	70	\$55,114.00
136	CAMPUS AVE	1001	1039	27	*1.5 grind and overlay	70	\$19,977.00
137	WABASH AVE	11001	11099	19	*Full Reconstruction (MINOR)	70	\$162,006.00
138	ARDMORE AVE	719	723	24	Full Reconstruction	69	\$14,461.00
140	COURIER AVE	401	431	30	*1.5 grind and overlay	69	\$9,490.00
142	LUGONIA AVE	299	319	42	*Mill + 2" RAC Overlay	69	\$19,082.00
143	POST ST	801	849	25	*1.5 grind and overlay	69	\$13,673.00
144	9TH ST	101	149	18	*Full Reconstruction (LOCAL)	69	\$14,618.00
145	TEXAS ST	801	837	64	LOCALIZED BASE REPAIR / REPAVE	69	\$36,816.00
146	COOK ST	1	99	35	*1.5 grind and overlay	69	\$9,668.00

**Matrix Method Priority List (First \$10 million only)**

Priority Rank	Street Name	From Address	To Address	PCI	Repair Type	Matrix Score	Repair Cost
147	CORNELL AVE	1201	1299	35	*1.5 grind and overlay	69	\$29,028.00
148	SAN MATEO ST	401	413	42	*Mill + 2" RAC Overlay	68	\$19,404.00
149	JUDSON ST	801	899	43	*Mill + 2" RAC Overlay	68	\$18,079.00
150	BROCKTON AVE	101	169	34	*Mill + 2" RAC Overlay	68	\$10,544.00
151	JUDSON ST	351	399	44	*Mill + 2" RAC Overlay	68	\$1,710.00
152	CITRUS AVE	301	317	80	Rubberized thin overlay	68	\$6,612.00
153	TENNESSEE ST	301	343	56	LOCALIZED BASE REPAIR / REPAVE	68	\$74,952.00
154	JUDSON ST	401	599	42	*Mill + 2" RAC Overlay	68	\$34,590.00
155	HIGHLAND AVE	423	439	55	*Rubberized THIN OVERLAY	68	\$9,318.00
157	GLENWOOD DR	501	553	61	LOCALIZED BASE REPAIR / REPAVE	68	\$24,998.00
158	COLTON AVE	501	525	42	*Mill + 2" RAC Overlay	68	\$14,190.00
159	WABASH AVE	745	799	82	LOCALIZED BASE REPAIR / REPAVE	68	\$19,497.00
160	HIGHLAND AVE	875	899	30	*Mill + 2" RAC Overlay	68	\$9,481.00
161	ALTA ST	1001	1037	35	*1.5 grind and overlay	68	\$12,038.00
162	PALM AVE	301	329	61	*Rubberized THIN OVERLAY	68	\$12,186.00
163	PARK AVE	1000	1098	28	2inch Grind Overlay	68	\$36,495.00
164	CYPRESS AVE	625	699	23	*Full Reconstruction (Major)	68	\$96,951.00
165	COLTON AVE	801	845	45	*Mill + 2" RAC Overlay	68	\$58,077.00
166	COLTON AVE	1	99	38	*Mill + 2" RAC Overlay	68	\$13,200.00
167	CYPRESS AVE	1101	1199	43	*Mill + 2" RAC Overlay	68	\$32,621.00
168	JUDSON ST	301	349	44	*Mill + 2" RAC Overlay	68	\$14,244.00
169	CAJON ST	601	659	38	2inch Grind Overlay	68	\$24,536.00
170	JUDSON ST	1301	1325	23	*Full Reconstruction (Major)	68	\$110,432.00
171	ALABAMA ST	41	49	57	*Rubberized THIN OVERLAY	68	\$12,406.00
172	COLTON AVE	1645	1663	57	*Rubberized THIN OVERLAY	68	\$25,698.00
173	UNIVERSITY ST	201	351	36	*Mill + 2" RAC Overlay	68	\$34,074.00
174	PALM AVE	901	959	31	*Mill + 2" RAC Overlay	68	\$11,184.00
175	JUDSON ST	727	799	42	*Mill + 2" RAC Overlay	68	\$19,830.00
176	FERN AVE	101	129	77	Rubberized thin overlay	68	\$8,497.00
177	CALIFORNIA ST	1201	1299	81	Rubberized thin overlay	67	\$19,174.00
178	CYPRESS AVE	1235	1243	50	*Mill + 2" RAC Overlay	67	\$18,784.00
179	OCCIDENTAL DR	1113	1121	21	Full Reconstruction	67	\$21,280.00
180	WESTERN AVE	101	199	63	LOCALIZED BASE REPAIR / REPAVE	67	\$21,120.00
181	PIONEER AVE	643	779	71	*Rubberized THIN OVERLAY	67	\$9,324.00
182	WESTERN AVE	1	99	73	LOCALIZED BASE REPAIR / REPAVE	67	\$21,120.00
183	COLTON AVE	991	999	38	*Mill + 2" RAC Overlay	67	\$5,265.00

**Matrix Method Priority List (First \$10 million only)**

Priority Rank	Street Name	From Address	To Address	PCI	Repair Type	Matrix Score	Repair Cost
184	TEXAS ST	701	799	64	*Rubberized THIN OVERLAY	67	\$15,461.00
185	OLIVE AVE	1501	1511	23	*Full Reconstruction (MINOR)	67	\$95,280.00
186	GARDEN ST	1401	1435	32	*Mill + 2" RAC Overlay	67	\$54,393.00
187	LYTLE ST	501	529	23	Full Reconstruction	67	\$97,843.00
188	CENTRAL AVE	601	627	24	Full Reconstruction	67	\$36,344.00
189	BERKELEY DR	801	899	26	*1.5 grind and overlay	67	\$13,367.00
190	PALM AVE	801	899	35	*Mill + 2" RAC Overlay	67	\$12,538.00
191	SAN MATEO ST	0	0	81	Rubberized thin overlay	67	\$7,843.00
192	BROCKTON AVE	901	917	40	*Mill + 2" RAC Overlay	67	\$5,952.00
193	NEVADA ST	11053	11099	81	Rubberized thin overlay	67	\$7,533.00
194	HIGHLAND AVE	21	157	32	*Mill + 2" RAC Overlay	67	\$21,230.00
195	HIGH AVE	801	809	22	*Full Reconstruction (LOCAL)	67	\$32,171.00
196	SUNSET DR	901	999	81	Rubberized thin overlay	67	\$20,729.00
197	OLIVE AVE	1601	1617	23	*Full Reconstruction (MINOR)	67	\$100,008.00
198	COURIER AVE	501	533	63	*Crack Repair and SLURRY SEAL	67	\$3,573.00
199	DIVISION ST	501	549	20	*Full Reconstruction (LOCAL)	67	\$24,960.00
200	CENTRAL AVE	1101	1149	25	Full Reconstruction	67	\$135,106.00
201	5TH AVE	1601	1649	40	*Mill + 2" RAC Overlay	67	\$31,380.00
202	CYPRESS AVE	1031	1047	38	*Mill + 2" RAC Overlay	67	\$21,734.00
203	SUNSET DR	801	899	81	Rubberized thin overlay	67	\$23,449.00
204	REDLANDS BLVD	2057	2069	49	*Mill + 2" RAC Overlay	67	\$38,124.00
205	6TH ST	1101	1163	76	Rubberized thin overlay	67	\$15,248.00
206	PIONEER AVE	113	229	72	*Rubberized THIN OVERLAY	67	\$7,482.00
207	OLIVE AVE	1619	1629	22	*Full Reconstruction (MINOR)	67	\$83,112.00
208	OLIVE AVE	1433	1495	24	*Full Reconstruction (MINOR)	67	\$86,160.00
209	CENTRAL AVE	1319	1339	73	CRACK FILL	67	\$563.00
210	ALABAMA ST	315	321	81.6	Rubberized thin overlay	67	\$5,644.00
211	WESTERN AVE	201	227	63	LOCALIZED BASE REPAIR / REPAVE	67	\$21,088.00
212	HERALD ST	1101	1163	73	Rubberized thin overlay	67	\$15,174.00
213	GARDEN ST	1555	1593	32	*Mill + 2" RAC Overlay	67	\$20,285.00
214	NEW YORK ST	101	249	30	*1.5 grind and overlay	67	\$39,836.00
215	OXFORD DR	801	825	32	2inch Grind Overlay	67	\$15,536.00
217	HIGHLAND AVE	841	873	30	*Mill + 2" RAC Overlay	67	\$6,369.00
218	TAMARISK ST	139	179	63	*Crack Repair and SLURRY SEAL	67	\$4,228.00
219	LYTLE ST	601	629	23	Full Reconstruction	67	\$59,202.00
220	CYPRESS CIR	625	659	15	*Full Reconstruction (LOCAL)	67	\$69,816.00

**Matrix Method Priority List (First \$10 million only)**

Priority Rank	Street Name	From Address	To Address	PCI	Repair Type	Matrix Score	Repair Cost
221	CLAY ST	1301	1343	30	*1.5 grind and overlay	67	\$20,170.00
222	HIGH AVE	811	869	16	*Full Reconstruction (LOCAL)	67	\$61,355.00
223	ROBINHOOD LN	401	403	24	Full Reconstruction	66	\$16,530.00
224	HEMLOCK CT	701	725	24	Full Reconstruction	66	\$53,525.00
225	MONTEREY ST	601	615	26	*1.5 grind and overlay	66	\$10,696.00
226	ESTHER WAY	521	539	28	*1.5 grind and overlay	66	\$10,994.00
227	SAN JACINTO ST	501	535	22	Full Reconstruction	66	\$77,022.00
228	ROMA ST	201	207	27	*1.5 grind and overlay	66	\$11,442.00
229	COLTON AVE	601	617	61	*Rubberized THIN OVERLAY	66	\$12,577.00
230	COLTON AVE	1301	1407	63	*Rubberized THIN OVERLAY	66	\$53,900.00
231	CYPRESS CIR	0	0	28	*1.5 grind and overlay	66	\$3,340.00
232	ROBINHOOD LN	405	429	24	Full Reconstruction	66	\$40,981.00
233	CYPRESS AVE	0	0	61	*Crack Repair and SLURRY SEAL	66	\$2,005.00
234	SUNSET DR	31012	31014	31	*Mill + 2" RAC Overlay	66	\$4,926.00
235	MONTEREY ST	617	631	26	*1.5 grind and overlay	66	\$10,152.00
236	SAN JACINTO ST	401	431	23	Full Reconstruction	66	\$71,142.00
237	DIVISION ST	601	649	18	*Full Reconstruction (LOCAL)	66	\$36,676.00
238	ASH ST	401	437	24	Full Reconstruction	66	\$79,498.00
239	STILLMAN AVE	1431	1439	26	*1.5 grind and overlay	66	\$8,054.00
240	SHARON RD	201	299	32	2inch Grind Overlay	66	\$16,471.00
241	DANA ST	701	725	16	*Full Reconstruction (LOCAL)	66	\$26,658.00
242	VIA VISTA DR	301	349	22	*Full Reconstruction (LOCAL)	66	\$23,262.00
243	ARROWVIEW DR	401	417	24	Full Reconstruction	66	\$43,355.00
244	COLTON AVE	501	517	61	*Rubberized THIN OVERLAY	66	\$12,443.00
245	MORRISON DR	1339	1359	24	Full Reconstruction	66	\$37,498.00
246	COLTON AVE	401	421	63	*Rubberized THIN OVERLAY	66	\$12,481.00
247	CORONADO DR	641	699	24	Full Reconstruction	66	\$25,637.00
248	COLTON AVE	311	319	38	*Mill + 2" RAC Overlay	66	\$5,117.00
249	HASTINGS ST	227	307	28	2inch Grind Overlay	66	\$16,756.00
250	ALTA VISTA DR	31536	31592	26	*Mill + 2" RAC Overlay	66	\$11,498.00
251	KEVIN AVE	965	995	26	*1.5 grind and overlay	66	\$7,435.00
252	EUCALYPTUS DR	201	207	26	*1.5 grind and overlay	66	\$7,825.00
253	JUANITA LN	1501	1649	26	*1.5 grind and overlay	66	\$17,281.00
254	CENTRAL AVE	917	999	24	Full Reconstruction	66	\$103,970.00
255	DEARBORN ST	801	899	62	*Rubberized THIN OVERLAY	66	\$14,499.00
256	FAWN CT	1441	1451	22	Full Reconstruction	66	\$29,994.00



**Matrix Method Priority List (First \$10 million only)**

Priority Rank	Street Name	From Address	To Address	PCI	Repair Type	Matrix Score	Repair Cost
257	SUSAN AVE	1301	1375	20	*Full Reconstruction (LOCAL)	66	\$112,742.00
258	MORRISON DR	1311	1323	24	Full Reconstruction	66	\$29,736.00
259	BROCKTON AVE	201	299	30	*Mill + 2" RAC Overlay	66	\$10,544.00
260	ALTA ST	1201	1259	72	Rubberized thin overlay	66	\$15,053.00
261	NEVADA ST	801	909	61	LOCALIZED BASE REPAIR / REPAVE	66	\$75,761.00
262	JEAN AVE	1301	1371	18	*Full Reconstruction (LOCAL)	66	\$112,683.00
263	WABASH AVE	351	399	24	*Full Reconstruction (MINOR)	66	\$77,582.00
264	ARDMORE AVE	725	739	24	Full Reconstruction	66	\$23,298.00
265	SUNSET DR	401	453	23	*Full Reconstruction (MINOR)	66	\$103,754.00
267	LYTLE ST	631	735	23	Full Reconstruction	66	\$89,096.00
268	JEFFERSON ST	451	569	27	*1.5 grind and overlay	66	\$12,240.00
269	TENNESSEE ST	101	287	68	*Rubberized THIN OVERLAY	66	\$59,068.00
270	FULBRIGHT AVE	1219	1259	20	*Full Reconstruction (LOCAL)	66	\$69,982.00
271	SAN RAFAEL ST	319	333	24	Full Reconstruction	66	\$31,382.00
273	ROMA ST	209	217	24	Full Reconstruction	66	\$22,042.00
274	FULBRIGHT AVE	1211	1217	20	*Full Reconstruction (LOCAL)	66	\$13,244.00
275	LA SOLANA CT	30828	30848	24	Full Reconstruction	66	\$30,262.00
276	GREENBRIAR CT	11	279	28	*1.5 grind and overlay	66	\$23,407.00
277	THE TERRACE	0	0	28	*1.5 grind and overlay	66	\$43,747.00
278	LUGONIA AVE	905	1051	27	*1.5 grind and overlay	66	\$19,895.00
279	INDEPENDENCE AVE	1623	1629	26	*1.5 grind and overlay	66	\$8,285.00
280	IDYLLWILD CT	707	725	24	Full Reconstruction	66	\$34,754.00
281	HERALD ST	1201	1259	82	Rubberized thin overlay	66	\$15,225.00
Total							\$9,950,651.00